



Tx/Rx Charger INSTRUCTIONS

FEATURES:

- Input: 110-240V ~ 50/60Hz
- Outputs:
 - Receiver (Rx) 4.8-8.4v/600mA (Peak Detect Charge Termination)
 - Transmitter (Tx) 7.2V/170mA (Constant Fixed Output)
- 2 Charge Indicators.
- Suitable for both Nickel Cadmium and Nickel Metal Hydride batteries.

OPERATION:

- Connect the charger to a 110-240V mains socket.
- Connect the battery/batteries to the selected outputs, ensuring correct polarity.
- Check that the corresponding LED is lit, showing that the battery is on charge;
 - Rx output will glow red whilst charging and then change to green when the battery reaches full charge.
 - Tx output will glow red whilst charging.
- To terminate charging, disconnect the battery/batteries from the charger, then unplug the charger from the mains supply.

WARNINGS:

- The charger must not be exposed to rain.
- Never try to charge non rechargeable batteries.
- Charging rechargeable batteries can generate explosive gases – prevent flames and sparks whilst charging.

Ripmax Ltd.,
241 Green Street,
Enfield, EN3 7SJ.
United Kingdom.

